Journeyman's Exam

Notification of exam location will be mailed two weeks before

Test starts at 8 a.m. 5 hour time limit

Extra material will be allowed but the 5 hour time limit will be enforced Shorts, sleeveless shirts and tennis shoes are not allowed Safety glasses are required


Grading schedule

Values

Phase

rnase			<u>v aiues</u>
Soil Pipe Project	-	Total	100 Points
Appearance	-		10 points
Alignment	-		10 points
Proper Torque	-		15 points
Proper Bands	-		15 points
Measurements	-		50 points
Copper Project	-	Total	100 points
Measurements	-		36 points
Pressure Test	-		34 points
Appearance	-		15 points
Alignment	-		15 points
Deductions will be given	ı as fo	llows:	
Missed measurements		- 6 points each	
Pressure test leak		- 35 points	
Reversed end fittings		- 10 points	
Written Test	-	Total	100 points
Drawing Pipe Sizing	-	Total	100 points

Copper Project



Material that you need to supply and have with you for this project

1 - ¾" X 3' type M copper pipe

1 - ¾" copper male adapter

1 - 3/4" copper cap

4 - ³/₄" copper 45 degree fitting

Sand Paper and Fitting Brush

Soldering Flux

Torch

Lead-free Solider

Tubing cutters

Tape measure

Level

Calculator


NOTE: Be prepared to construct the above project with the above fittings and a limited number of measurements are giving.

BRING SAFETY GLASSES THAT MUST BE WORN AT ALL TIMES

Cast Iron Project

(NOT ACTUAL SIZE)

Fittings and Pipe will be supplied



Material that you need to supply and have with you for this project

11 - 1½"No-Hub Clamps
Torque Wrench
Tape Measure
Level
Calculator

NOTE: Be prepared to construct the above project with the above fittings and a limited number of measurements are giving.

BRING SAFETY GLASSES THAT MUST BE WORN AT ALL TIMES